

LIST OF FIGURES

Figure-1.1 World crude steel production scenario of the top ten countries	1
Figure-1.2 Steel making technology in India and world.....	2
Figure-1.3 Distribution of steelmaking raw materials in India	3
Figure 2.1 Flow chart for preparation and characterization of raw materials	233
Figure 2.2 Jaw and Roll Crusher used to crush raw materials up to fines of (-1mm)	255
Figure 2.3 Ball Mill used to grind iron ore into powder	266
Figure 2.4 Set up used for particle analysis of iron ore	Error! Bookmark not defined.
Figure 2.5 X-Ray Diffraction pattern of iron ore.....	31
Figure 2.6 Particle Size Analysis of Iron Ore fines	32
Figure 3.1 Flow chart for preparation and characterization of highly flux hardened iron ore pellets	344
Figure-3.2 Air dried fluxed iron ore pellets	355
Figure-3.3 Hardening cycle used for fluxed iron ore pellets	366
Figure-3.4 Physical changes of iron ore pellet: a) Before hardening (Oven dried pellets); b) During hardening (In the Furnace); c) After hardening (Hardened pellets).	377
Figure 3.5 Effect of basicity and temperature on properties of hardened flux pellets: a) Crushing strength; b) Porosity; c) Density;	411
Figure 3.6 Phase analysis of highly flux hardened pellets with basicity 2, 4, 6, 8. (1-Hematite, 2-Calcium Di-ferrite, 3-Calcium ferrite).....	433
Figure 3.7 Binary phase diagram of CaO and Fe ₂ O ₃	444
Figure 3.8 SEM images of highly flux hardened pellets at 5000X magnification.....	455
Figure 3.9 SEM images of highly flux hardened pellets at 1000X magnification.....	466
Figure 3.10 SEM images of highly flux hardened pellets at 100X magnification: a) 6 basicity at 1180°C ; b) 6 basicity at 1200°C ; c) 8 basicity at 1180°C; d) 8 basicity 1200°C .	477
Figure 4.1 Flow chart for reduction and characterization of hardened flux iron ore Pellets	51
Figure-4.2 Reduction Cycle used for hardened flux iron ore pellets	522
Figure-4.3 Schematic diagram of the crucible and resistance heating furnace used in the experimental study: a) Resistance heating furnace; b) Crucible arrangement.....	533
Figure-4.4 condition of crucibles: a) before reduction; b) during reduction; c) after reduction	533
Figure- 4.5 Effect of temperature on the reduction behavior of iron ore pellets for: a) 2 basicity; b) 4 basicity; c) 6 basicity; d) 8 basicity	Error! Bookmark not defined.
Figure-4.6 Effect of basicity on the reduction behavior of iron ore pellets at temperature: a) 900°C; b) 950°C; c) 1000°C; d) 1050°C	59
Figure -4.7 Effect of Basicity on the Rate of Reduction for fluxed iron ore pellets at temperature: a) 900°C; b) 950°C; c) 1000°C; d) 1050°C	611
Figure-4.8 Topo graphical representation of reduction behavior of iron ore pellet.....	622

Figure-4.9 Effect of Temperature and Basicity on the Metallization a) 900°C, b) 950°C, c) 1000°C, d) 1050°C..... 633

Figure-4.10 Comparative study of the phases; a) phase analysis of pellets (before reduction) X-ray source Cu-K α ; b) phase analysis of pellet (after reduction) X-ray source Co-K α 644

Figure-4.11 SEM images of highly flux hardened iron ore pellets reduced at 1000°C for 1 hour at 2000 X Magnification: For a) 2Basicity; b) 4Basicity; c) 6Basicity; d) 8Basicity 666

Figure-4.12 EDS images of highly flux reduced iron ore pellets at 1000°C for 1 hour. 666

Figure-4.13 Model fitting curve for activation energy calculation: a) 2 basicity; b) 4 basicity; c) 6 basicity; d) 8 basicity..... 711

Figure-4.14 Arrhenius Plot and Activation energy values for basicity 2, 4, 6 and 8 iron ore pellets reduced at temperature 900, 950, 1000 and 1050°C..... 733

Figure-5.1 Arrangement of samples during weathering test; a) DRI on glass dishes with number; b) Hollow packing carton as cover 777

Figure-5.2 Moisture gain of DRI with respect to weathering time; a) 4 basicity DRI, b) 6 basicity DRI, c) 8 basicity DRI..... 822

Figure-5.3 Volume change of DRI with respect to weathering time; a) 4 basicity DRI, b) 6 basicity DRI, c) 8 basicity DRI 833

Figure-5.4 Physical appearance of DRI with respect to weathering time..... 844

Figure-5.5 a) X-Ray Diffraction pattern of 6 & 8 basicity DRI pellets (~98%R) before and after weather test, b) FTIR spectrum of 8basicity ~98%R weathered DRI (pellet).....84

Figure-5.6 SEM/EDS analysis of cracked DRI; a) Cracked DRI, b) Morphology of spotted area, c) EDS of spots away from the crack, d) EDS on one side of the crack, e) EDS on another side of the crack 855

Figure-5.7 Tentative mechanism of crack formation; a) Fresh DRI, b) DRI after 30 days (external crack), c) DRI after 60days (internal crack), d) DRI after 60 days (internal crack propagation) e) Schematic presentation of the sample..... 866

Figure-5.8 Possible reactions of iron and calcium with oxygen and hydrogen 888

Figure 6.1 Sectional view of Electric arc furnace (Conventional Type) 911

Figure 6.2 Coil along with current induced arrangement and Sectional view of conventional induction furnace. 933

Figure-6.3 Raw materials used for the study: a) Lime powder; b) DRI; c) Pig-Iron..... 944

Figure-6.4 Diagram of furnace used to melt the material: a) Isometric diagram, b) Schematic diagram of cross sectional view 955

Figure-6.5 Melting cycle used for the experiment..... 966

Figure-6.6 Behavior of removal of impurities with reaction time under different conditions during electric arc melting: a) for 20 minute Exposure time; b) Silicon; c) Manganese; d) Carbon; e) Phosphorus; f) Sulphur 988

Figure-6.7 Rate of removal of impurities (%/minute): a) EAF; b) Silicon; c) Manganese; d) Carbon; e) phosphorus; f) Sulphur..... 1055

Figure-6.8 Rate of removal of impurities (%/minute) for different % R fluxed DRI feed: a) EAF; b) 30%R; c) 50%R; d) 80%R.....	1077
Figure-6.9 Photographs of furnace used to melting studies: a) Isometric view, b) Cold Charging, Melting & Sampling; c) Pouring into crucible.....	1099
Figure-6.10 Melting cycle used for the experiment.....	110
Figure-6.11 Behavior of removal of impurities with reaction time under different conditions during electric induction melting: a) Melting conditions; b) Silicon; c) Manganese; d) Carbon; e) Phosphorus; f) Sulphur	1122
Figure-6.12 Rate of removal of impurities (%/minute): a) Ind. F/c; b) Silicon; c) Manganese; d) Carbon; e) Phosphorus; f) Sulphur	1155
Figure-6.13 Rate of removal of impurities (%/minute) for different % R fluxed DRI feed: a) Ind. F/c; b) Only free lime; c) 50%R fluxed DRI; d) 80%R fluxed	1177
Figure-6.14 Melting cycle used for the present study.....	12020
Figure-6.15 Schematic diagram of plasma arc furnace setup and different interphases arrangements during steelmaking	12121
Figure-6.16 Behavior of removal of impurities under different plasma conditions during melting in electric arc furnace.....	1233
Figure-6.17 Behavior of removal of impurities under different mode of Lime charging during melting in electric arc under N ₂ Plasma furnace	1244
Figure-6.18 Schematic diagram of an imaginary distinct layers/interfaces, elements and reactions involved during removal of impurities from pig iron in an EAF.	1277