

List of Figures

Figures	Page No.
Fig. 1.1 Global Production of PMs	5
Fig. 1.2 Applications of PMs	5
Fig 1.3 Cost of Permanent Magnets over years	6
Fig. 1.4 Classification of PM Machines	10
Fig 1.5 Rotor Topologies (a) SMPM (b) SIPM (c) IPM without flux barriers (d) IPM with flux barriers	11
Fig. 1.6. Radial Flux PM Machine (a) Construction (b) Direction of flux	13
Fig. 1.7 Axial Flux SMPM Machine (a) Construction (b) Direction of flux	13
Fig. 1.8 Methods of Analysis for PM Machines	15
Fig. 2.1 Distribution of Magnetization of Permanent Magnets	34
Fig 2.2 A Typical 12-slot Surface Mounted PM motor	39
Fig. 2.3 Linear Model of PM motor (a) with slots and PMs (b) slots neglected	39
Fig. 2.4 Simplified Linear Model of the Surface Mounted PM Machine (a) Isotropic (b) Anisotropic	40
Fig 2.5 Typical layer models of PMBL motor- (a) Isotropic model- stator winding is replaced by linear current density $j_P(x)$ and PM layer are represented by linear current density $j_S(x)$ (b) Anisotropic layer model of PMBL motor taking slots and slot openings into account. (Current sheets are assumed to be infinitesimally thin)	41
Fig 2.6 Variation of Torque with displacement angle	49
Fig. 2.7 Location of pole in the ξ -plane	49
Fig. 2.8 Typical variation of torque integrands of PMBLAC motor at (a) standstill (b) 400 RPM (c) 800 RPM	50
Fig. 2.9 Analytical Model for calculating cogging torque	54
Fig. 3.1 Rotor Position Sensing Methods for PMBL Machines	60
Fig. 3.2 PM Enhanced Sensing Scheme for Rotor Position Sensing	61
Fig. 3.3 (a) Inner stator (windings not shown for clarity) (b) Outer Hub Rotor	61
Fig. 3.4 Parts of the prototype RFPM Motor	63
Fig. 3.5 Complete setup of the 12-slot 12-pole SMPM motor	63
Fig. 3.6 Typical arrangement of the AFPM machine with PM rotor on one side	69

Figures	Page No.
and Al sheet rotor on the other	
Fig. 3.7 (a) Stator with semi-closed slots (b) Stator with concentrated windings	69
Fig. 3.8 Dimensions of arc shaped PMs used (all measurements are in mm)	70
Fig. 3.9 (a) Solid disc Rotor (b) Four Pole PM Rotor (c) Six Pole PM Rotor	70
Fig. 3.10 Slot star of the windings (a) 5-phase 10-slot 4-pole (b) 5-phase 10-slot 2-pole (c) 3-phase 12-slot 4-pole	71
Fig. 3.11 Experimental set up of Machine B	72
Fig.3.12 Amplified auxiliary winding EMF and main winding EMF (Time/div=100 ms, Volt/div=5 V)	75
Fig. 3.13 Amplified auxiliary winding EMF and main winding EMF when machine is loaded (Time/div= 100 ms, Volt/div= 5 V)	75
Fig. 3.14 (a) Shadow coil and main winding EMF induced in the one of the phase of Machine-B (Time/div= 50 ms, Volt/div= 1 V) (b) Current and respective amplified EMF in one of the phase of Machine B on load (Time/div= 5.0 ms, Volt/div= 15V, Amp/div=0.2A)	76
Fig. 3.15 Speed induced EMF at (a) 130 rpm (Time/div= 25 ms, Volt/div= 2 V) (b) 618 rpm (Time/div= 10 ms, Volt/div= 2 V)	76
Fig. 3.16 Effect of air gap on the induced EMF at (a) 12 mm (b) 9 mm (Time/div= 25 ms, Volt/div= 2 V)	76
Fig. 3.17 (a) Shadow coil and main winding EMF induced in the one of the phase of Machine -C (Time/div= 25 ms, Volt/div= 1/2 V) (b) Current in one of the phase of Machine C on load (Time/div= 10 ms, Amp/div= 0.2A)	77
Fig. 3.18 Speed induced EMF at (a) 370 rpm (b) 450 rpm (Time/div= 10 ms, Volt/div= 1V)	77
Fig. 3.19 Effect of air gap on the induced EMF at (a) 15 mm (Time/div= 10 ms, Volt/div= 1V) (b) 11 mm (Time/div= 10 ms, Volt/div= 2V)	77
Fig. 3.20 Back-EMF induced in the main winding of Machine-D (Time/div= 25 ms, Volt/div= 5 V)	78
Fig. 3.21 Main coil EMF and search coil EMF of Machine-D (Time/div= 50 ms, Volt/div= 5V)	78
Fig. 3.22 Current waveform of Machine-D (Time/div= 10 ms, Amp/div= 0.2 A)	78

Figures	Page No.
Fig. 4.1 Typical Torque-Speed Characteristics of PM Motor	83
Fig. 4.2 Torque-Speed Characteristics from experimental and analytical calculation at constant voltage at V=30V	84
Fig. 4.3 Torque-Speed Characteristics calculated by Residue Theorem at two different stator supply voltages	84
Fig. 4.4 Flux density distribution along air gap with and without slotting effect using Residue Method and its validation by FEM	85
Fig. 4.5 Validation of calculated Back EMF from Residue Method and Experimental Results for Machine-A	85
Fig 4.6 Effect of variation of PM thickness and air gap on Torque-Speed Characteristics of Machine-A	86
Fig. 4.7 Effect of different of type of PMs on Torque-Speed Characteristics of Machine-A	86
Fig. 4.8 Torque-Speed characteritics of the Machine-B in healthy condition	89
Fig. 4.9 Torque-Speed characteritics of the Machine-B with one faulty phase	89
Fig. 4.10 Torque-Speed characteritics of the Machine-B with two faulty phases	90
Fig. 4.11 Torque-Speed characteritics of the Machine-C in healthy condition	90
Fig. 4.12 Torque-Speed characteritics of the Machine-C with one faulty phase	91
Fig. 4.13 EMF vs Speed for Machine-C	91
Fig. 4.14 Torque-Speed Characteristics obtained from experimental setup and Residue Method	92
Fig. 4.15 Torque Vs Stator Current Characteristics	92
Fig. 4.16 Comparison of EMF induced at different speeds and calculated from the Residue Method	93
Fig. 4.17 Variation of cogging torque with angular displacement	93
Fig. 4.18 Torque-speed characteristics for RFPM motor-Machine-A obtained from various methods and its validation with experimental results	96
Fig. 4.19 Torque-speed characteristics of Machine-B	96
Fig. 4.20 Torque-Current characteristics calculated by different analytical methods for Machine-B	97
Fig. 4.21 Air gap flux density comparison obtained for Machine-B	97
Fig. 4.22 Torque-Speed Characteristics of Machine-B under healthy and faulty	98

Figures	Page No.
condition	
Fig. 4.23 Torque-Speed Characteristics of Machine-C under healthy and faulty condition	98
Fig. 4.24 Performance Comparison of five phase AFPM motors	99
Fig. 4.25 Current Vs Speed variation of five phase AFPM motors	99